

Lacquer 200 ml and Stick Lacquer 20 ml Operation Manual

Before lacquering you should:

- prepare painted surface, degrease a place for painting with means of degreasing agent.
- when damage is too deep, you should use epoxy primer to protect it against corrosion.
- mix the paint in the package by shaking it for about one and a half minute.
- application brush is located in the closing of paint package.
- make the painting with small amount of paint, to compare the paint tone with colour of painted surface.
- place two to three thin layers of paint and maintain about 2 minutes intervals between placing subsequent layers, according to environmental conditions.
- painting temperature is + 5C to 25C with regard to air humidity. Paint obtains its full properties

after 24 hours.